



**SLEEVE MANUAL**



# **TECH SLEEVES**

**THE FUTURE IS NOW**



**[WWW.TECH-SLEEVES.COM](http://WWW.TECH-SLEEVES.COM)**

# HOW TO DEMOUNT THE TAPE AND PLATE OFF THE SLEEVE?

## 1 SPREAD FORCE EQUALLY

Spread equal force along the width of the plate or tape while demounting it.



## 2 DO NOT USE EXCESSIVE PRESSURE ON THE EDGES

Avoid putting excessive pressure towards the edges. This may cause damage.



## 3 CLEAN THE SLEEVE

Don't let the ink stay on the sleeve for a long duration. Clean the sleeve immediately after usage and store it.



## 4 USE DEMOUNTER

Using a Demounter is the most efficient and safe way of removing plates and tape from a sleeve.



For more information visit [www.tech-sleeves.com](http://www.tech-sleeves.com).



# WORLDWIDE CUSTOMIZED SLEEVE SOLUTIONS

Tech Sleeves offers Bridge and Plate Sleeves for the global flexographic printing industry. We strive to enhance the printing quality and overall efficiency through a combination of experience and innovation.



**TECH SLEEVES**  
THE FUTURE IS NOW

H. Kamerlingh Onnesweg 2, 2408 AW Alphen aan den Rijn  
P.O. Box 252, 2400 AG Alphen aan den Rijn, The Netherlands

T 0031 172 503611 | F 0031 172 437919 | E [info@tech-sleeves.com](mailto:info@tech-sleeves.com)

[WWW.TECH-SLEEVES.COM](http://WWW.TECH-SLEEVES.COM)



@techSleeves